

# H3020

Model: H3020

Temperature and Humidity Sensor

Temperature range: -40°C to 70°C, Humidity range: 0% to 100% RH



□□□□