

031-60, Ni100



SN130

Ni1000/6180

-10 to 60°C.

$\pm(0.3+0.005*|t|)$.

CINCH